Approved For Release 2000/04/20: CIA-RDP33-02415A000200240023-7

SAPC 251/ Copy _of 6

10 **November** 1955

MEMORANDUM FOR THE RECORD

SUBJECT: MATS Shuttle Maintenance

25X1A6a

reported to me that one of the two maintenance men supplied to MATS from San Bernardino for the abuttle was replaced by an 25X1A6a inexperienced man. This change has resulted in insufficient care of the C-54 and consequently several times the aircraft has been delayed in taking off because of mechanical failue. The Base Commander considers this a serious matter and asks Headquarters assistance in contacting Colonel Berg to effect pressure on San Bernardino to supply MATS with competent maintenance personnel.

